

HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS

HAER
WASH
3-RICH.V
3A-

Reduction-Oxidation Complex,
Plutonium Concentration Facility (Building 233-S)
200 West Area, Hanford Site
Richland Vicinity
Benton County
Washington

HAER No. WA-129-A

Mark Roberts, Photographer, Boeing Computer Services-Richland, Hanford Site,
January 1995.

- WA-129-A-1 West facade of Plutonium Concentration Facility (Building 233-S),
Reduction-Oxidation Building (REDOX - 202-S) to the right.
Looking east.
- WA-129-A-2 West facade of Building 233-S. Looking east.
- WA-129-A-3 Contextual view of 233-S and 202-S (in background). Looking
southwest.
- WA-129-A-4 233-S and 202-S (in background). Looking south.
- WA-129-A-5 East facade of 233-S (in background). 202-S to the left. Looking
west.
- WA-129-A-6 East facade of 233-S. 202-S to the left. Looking west.
- WA-129-A-7 Close-up of east facade of 233-S. 202-S to the left. Looking
west.
- WA-129-A-8 Control Room for the Process Hood Areas. Control panel on the
right. Looking north.
- WA-129-A-9 Control Room for the Process Hood Areas. Control panel on the
left. Looking south.

Photograph numbers ^{129-A}WA-10 through ^{129-A}WA-13 are photocopies of
engineering/construction drawings. The original documents are located in the
Division of Micrographics, Boeing Computer Services-Richland (BCSR), Federal
Building, Richland, Washington. WA-129-A-10 through WA-129-A-13 are 8"x10"
enlargements from 4"x5" negatives.

WA-129-A-10 *Architectural Door Details & Plot Plan, 233-S, U. S. Atomic Energy
Commission, Hanford Atomic Products Operations, General
Electric Company, Dwg. No. H-2-30469, 1956.*

- WA-129-A-11 *Architectural Elevations & Sections*, 233-S, U. S. Atomic Energy Commission, Hanford Atomic Products Operations, General Electric Company, Dwg. No. H-2-30465, 1956.
- WA-129-A-12 *Architectural Floor Plans*, 233-S, U. S. Atomic Energy Commission, Hanford Atomic Products Operations, General Electric Company, Dwg. H-2-30464, 1956.
- WA-129-A-13 *Elevations*, 233-S, U. S. Atomic Energy Commission, Hanford Works, General Electric Company, Dwg. No. H-2-7203, 1956.

Large-format views of the interior of 233-S were not conducted due to health and safety concerns, and potential for damage to large-format cameras. (There was a possibility of airborne contamination inside the building.) 35-mm photographs of the interior of 233-S are located in the Field Records section of this submittal.